

IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF: U.S. Patent No. 7,414,443

USPTO CONFIRMATION CODE: 5505

APPLICATION NO.: 10/581,787

PCT FILED: December 10, 2003

U.S. FILED: June 06, 2006

EXAMINER: N. Drew Richards

GROUP ART UNIT: 2816

FOR: FREQUENCY MULTIPLIER

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION
FOR USPTO AND/OR APPLICANT MISTAKE

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

SIR:

The following is a request for a certificate of correction in Serial Number 10/581,787, now Patent Number 7,414,443.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to our Deposit Account No. 50-1379.

The exact locations where the errors appear in the patent and patent application are as follows:

In Column 1, below Title, insert - - This application is the US national phase of international application PCT/SE2003/001919 filed 10 December 2003, which designated the U.S., the entire contents of which are hereby incorporated by reference. - -.
(AMENDMENTS TO THE SPECIFICATION DATED JUNE 6, 2006, PAGE 3, LINES 2-5)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

03/27/2009

DATE

/SIDNEY L. WEATHERFORD, Reg#45602/

Sidney L. Weatherford
Registration No. 45602
Attorney of Record